



# SIoux LOOKOUT

## Hub of the North

The Corporation of the  
Municipality of Sioux Lookout  
25 Fifth Avenue, P.O. Box 158  
Sioux Lookout, Ontario • P8T 1A4  
Telephone: (807) 737-2700  
Facsimile: (807) 737-3436  
www.siouxlookout.ca

### Development Services Department

August 26, 2024

Dear Sir/Madam:

**Re: Request for Quote – Invasive Asbestos Audit and Designated Substance Survey –  
Lost Lake Centre and the Hudson Community Centre – RFQ - Q018-2024**

The intent of this invasive asbestos audit and designated substance survey is to sample different building materials in each facility to determine if asbestos containing materials (ACM) and designated substances exist. All sampling and work to be completed in accordance with O Reg 278/05. The buildings may be demolished in the future, the findings of this survey will help to estimate the future costs of these demolitions.

**The Consultant Shall:**

Complete an assessment of each property in order determine if ACM is suspected or present.

Take samples as needed and complete the necessary testing to confirm or deny the presence of ACM.

Determine if the following substances are suspected or present:

- Mold
- Lead
- Mercury
- UFFI (Urea Formaldehyde Insulation)

**The Lost Lake Centre is heated by an oil-fired furnace. Please investigate the area around the oil tank and furnace to determine if there is evidence of fuel oil contamination beyond the building envelope.**

Provide a final report which list if any ACM or designated substances are found, provide details on the location and amount of the affected material. Provide information about the friability and condition of the affected material. If any designated substances are found, provide details on the location and amount of the affected materials. Include recommendations on properly disposing any designated substances found. Provide a recommendation as to whether or not additional investigations are needed to determine if there is fuel oil contamination.

Complete the work no later than December 20<sup>th</sup>, 2024.

### **The Municipality Shall:**

Provide the opportunity for the proponent to view the sites during regular business hours during the RFQ phase.

Included with the RFQ are building details and pictures of each facility and a non-invasive asbestos audit for the Lost Lake Centre and Community Hall.

Municipal staff will repair any area damaged or opened up areas resulting from the invasive investigative process.

Please forward your written quote clearly marked “**Quote for Invasive Asbestos Audit**” by **10:00 am local time, September 17<sup>th</sup>, 2024** to (email submissions are permitted):

Jody Brinkman, Manager of Development Services  
Municipality of Sioux Lookout  
PO Box 158, 25 Fifth Avenue, Sioux Lookout ON. P8T 1A4  
Fax: 807-737-3436 Phone: 737-2700 ext. 2244 Email: [cbo@siouxlookout.ca](mailto:cbo@siouxlookout.ca)

### **21 Second Street, Hudson – Lost Lake Centre:**

Original construction date is unknown, approximately 3000sqft wood framed construction with a full basement and concrete foundation.
















**29 Second Street, Hudson – Community Hall:**

The Hudson Community hall was constructed during the 1970's and is approximately 4,000sqft. Slab on grade.









Please contact the undersigned if you have any questions or need clarification on anything. All responses will be forwarded to all firms partaking in the RFQ process.

Thank you for your interest and we look forward to receiving your quote.

Sincerely,  
**The Corporation of the  
Municipality of Sioux Lookout**



**Jody Brinkman**  
Manager of Development Services  
Development Services Department

Attachments:  
Lost Lake Centre – Asbestos Audit  
Community Hall – Asbestos Audit





Project No. 17-266-15

December 19, 2017

VIA EMAIL: ([cbo@siouxlookout.ca](mailto:cbo@siouxlookout.ca))

Mr. Jody Brinkman  
Manager of Development Services  
Municipality of Sioux Lookout  
PO Box 158, 25 Fifth Avenue  
Sioux Lookout, ON P8T 1A4

Dear Mr. Brinkman:

**Re: Asbestos Audit  
Community Hall  
29 Second Street, Hudson, Ontario**

True Grit Engineering (TGE) is pleased to provide to the Municipality of Sioux Lookout the results of a baseline asbestos audit (AA) for the Community Hall located at 29 Second Street in Hudson, Ontario. The AA was requested by Mr. Jody Brinkman, Manager of Development Services for the Municipality of Sioux Lookout, and TGE understands that it was requested in order to meet the requirement under Ontario Regulation 278/05 (O. Reg. 278/05), *Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations*, for an inventory of asbestos-containing materials (ACM) for the building.

### Summary

ACM were confirmed to be present in the subject building. None of the identified ACM were observed to be in poor condition or fallen.

TGE provides recommendations for ongoing management of ACM in the subject building.

### Background and Methodology

The Community Hall is a single storey, slab on grade, building with a large open concept gymnasium, a kitchen, washrooms and storage rooms. TGE understands that the subject building was constructed in or around 1970.

Asbestos was used widely in building materials prior to 1995. Typical asbestos-containing building materials include, but are not limited to, thermal system insulation (TSI), flooring, plaster, stucco, mud joint compound (MJC) associated with finished drywall and ceiling tiles (CT). Building materials containing asbestos can still be purchased for limited applications (e.g. high temperature or corrosive applications); however, asbestos is not expected to be found in most building materials purchased and installed after 1995.

A site visit to the subject building was completed by Mr. Mike Broere, TGE Air Quality Scientist and Ms. Layla Miller, TGE Engineer-in-Training, on December 7, 2017. The site contact was Mr. Richard Fenelon, Facilities Division Supervisor, Municipality of Sioux Lookout. Since this AA was a baseline audit the inspection was minimally invasive and hidden areas, such as those above or behind solid finished ceilings or walls, were viewed where accessible. Samples were not collected where sample collection would compromise the integrity of the subject building or cause unsightly damage to finished surfaces.

1263 Innovation Drive, Thunder Bay, ON, P7B 0A2

Tel: (807) 626-5640 | Fax: (807) 623-5690

[www.truegriteng.com](http://www.truegriteng.com)

A visual inspection of functional spaces and rooms in the subject building was conducted to identify materials that could contain asbestos. Potential ACM observed during the site investigation were identified as either friable or non-friable. Friable material is defined in O. Reg. 278/05 as a material that when dry, can be crumbled, pulverized or powdered by hand pressure alone or one that exists in a crumbled, pulverized or powdered state. Additionally, the quantity and condition of potential ACM were noted during the site visit.

Building materials suspected of containing asbestos were collected and sampled in accordance with O. Reg. 278/05. Samples were analyzed via Polarized Light Microscopy (PLM) following the U.S. Environmental Protection Agency Test Method EPA/600/R-93/116: *Method for the Determination of Asbestos in Bulk Building Materials*, June 1993. Where samples consisted of more than one distinct layer (i.e. vinyl floor tile, paper-type backing, mastic, etc.), each layer was analyzed and reported separately.

Materials found to contain 0.5% or more asbestos were identified as ACM (as per Ontario Regulation 278/05). The attached summary table contains the results of analysis along with the condition, quantity and friability of identified ACM.

## Results

A table of asbestos results, photographs and field notes, including a site plan sketch with sample locations indicated, and a laboratory Certificate of Analysis, are attached. Following is a brief summary of the results of the AA for the subject building:

- Non-friable ACM are present in the Hudson Community Hall.
- Additional ACM may be present in areas of the subject building that were not part of the baseline AA or were hidden from view.
- ACM in poor condition were not observed in the subject building.

## Conclusions and Recommendations

Based on the results of the AA for the Hudson Community Hall, TGE presents the following conclusions and associated recommendations (recommendations are shown in italic font):

- ACM are present in the Hudson Community Hall and the requirements described in O. Reg. 278/05 apply to the subject building.
- This report meets the requirement under O. Reg. 278/05 for an inventory of ACM for the subject building.
- *Keep a copy of this report on site.*
- *The building owner should be aware of his responsibilities regarding the identified ACM under O. Reg. 278/05, such as the requirement for regular (i.e. annual) inspections, notification of workers and/or employees and precautions that must be taken when handling or disturbing identified ACM.*
- *ACM in good condition and undisturbed do not have to be removed from a building.*
- *Avoid unnecessary disturbance of ACM. Develop work procedures that will accommodate the presence of ACM.*



- *Provide asbestos awareness training for any employees whose work may involve disturbance of ACM.*
- *Provide a copy of this report to contractors when tendering or completing renovation or demolition work.*
- *If renovations are planned for the subject building then prepare a drawing showing the general location of identified ACM and provide the drawing to contractors when tendering or completing renovation or demolition work.*
- *Any demolition or renovation work involving identified ACM must follow the work procedures outlined in O. Reg. 278/05.*
- *Prior to beginning any renovations, including demolition, complete a fully invasive asbestos audit (AA) for the renovation area. In particular, be aware that the following potential ACM may be present:*
  - *insulating material inside of hollow metal doors;*
  - *sealants or caulking materials around windows, doors or equipment penetrations through walls or the roof;*
  - *insulating material behind or above solid walls and ceilings;*
  - *multiple layers of flooring including flooring that may be present under wooden subfloor material; and*
  - *insulating materials inside pumps, boilers, furnaces, valves, tanks, flanged pipe fittings, motors, transformers, generators or other equipment.*
- *Notify contractors that if, during the course of renovations or demolition, suspected ACM is encountered, all work should cease immediately and the material should be sampled and analyzed to determine whether it contains asbestos.*
- *Asbestos waste must be transported by a Ministry of the Environment and Climate Change (MOECC) - licensed carrier to a licensed landfill willing to accept it.*

#### **Limitations**

The information and data contained in this report, including without limitation, the results of any sampling and analyses conducted by TGE pursuant to its Agreement with the client, have been developed or obtained through the exercise of TGE's professional judgment and are set forth to the best of TGE's knowledge, information and belief. Although every effort has been made to confirm that this information is factual, complete and accurate, TGE makes no guarantees or warranties whatsoever, whether expressed or implied, with respect to such information or data.

The information and data presented in this report are based on the purpose and scope of the project and form the basis for any conclusions and recommendations presented herein. Any conclusions and recommendations presented herein do not preclude the existence of environmental concerns other than those that may have been identified.

Work performed by TGE personnel employed sound environmental assessment principles. TGE cannot guarantee the accuracy and reliability of information provided by others or third parties. Therefore, TGE does not claim responsibility for undisclosed environmental concerns or conditions that may result in costs for environmental clean-up and/or remediation. This report is intended for information purposes only.



Mr. Jody Brinkman  
Municipality of Sioux Lookout  
Asbestos Audit Report - Hudson Community Hall  
Project No. 17-266-15  
December 19, 2017

**Closure**

We trust this is sufficient for your current requirements. If you have any questions or require further information, please do not hesitate to contact the undersigned at 807.285.9005.

Sincerely,

**TRUE GRIT ENGINEERING**

---

Jacquie Elvish, B.Sc., CRSP  
Senior Health and Safety Specialist  
[jelvish@truegriteng.com](mailto:jelvish@truegriteng.com)

JE/LM/MB:ls

Enclosures:     Table of Asbestos Results  
                      Photographs  
                      Field Notes (including a site sketch with sample locations)  
                      Laboratory Certificate of Analysis





**Table of Asbestos Results for Hudson Community Centre**

1263 Innovation Drive, Thunder Bay, ON, P7B 0A2  
Tel: (807) 626-5640 | Fax: (807) 623-5690

[www.truegriteng.com](http://www.truegriteng.com)

Table 1. Summary of Asbestos Information Community Hall 29 Second Street, Hudson, ON December 7, 2017					
Material Type <sup>1</sup> (Sample reference #)	Description and Location <sup>2</sup>	Asbestos Containing? (Method) <sup>3</sup>	Asbestos Content and Friability <sup>4</sup>	Condition <sup>4</sup>	Estimated Total Qty <sup>4</sup>
Reported date of construction is in or around 1970.					
<b>Identified Asbestos-Containing Materials (ACM)</b>					
VFT (HCH – S2)	9"x9", pink/grey VFT with white streaks observed in Room 3.	YES (LA)	1-10% Chrysotile Non-Friable	Good to fair	19.5 m <sup>2</sup>
VFT (HCH – S6)	9"x9", green/grey VFT with streaks observed in Rooms 8 and 9.	YES (LA)	>75% Chrysotile Non-Friable	Good to fair	7.61 m <sup>2</sup>
O (HCH – S7)	Grey fibrous ceiling boards observed above the CTs in Rooms 4 to 7.	YES (LA)	25-50% Amosite Non-Friable	Good	64.3 m <sup>2</sup>
<b>Identified Non-ACM</b>					
VFT (HCH – S1)	12"x12", grey VFT with white streaks observed in Room 1.	NO (LA)	--	--	--
Mastic (HCH – S2)	Mastic under 9"x9" pink/grey VFT with white streaks observed in Room 3.	NO (LA)	--	--	--
VFT (HCH – S3)	12"x24", VFT with beige tile pattern observed in Room 4.	NO (LA)	--	--	--
VFT (HCH – S4)	12"x12", grey/brown VFT with white streaks and flecks observed in Rooms 5 to 7.	NO (LA)	--	--	--
MJC (HCH – S5)	Mud joint compound associated with finished gypsum board walls observed in Rooms 4 to 7.	NO (LA)	--	--	--
Mastic (HCH – S6)	Mastic under 9"x9" green/grey VFT with streaks observed in Rooms 8 and 9.	NO (LA)	--	--	--
O (HCH – S8)	Black asphalt shingle covering located on the exterior walls of the subject building.	NO (LA)	--	--	--
O	Wood fibre boards observed on the walls and ceilings in Rooms 1 to 3 and 8 to 9.	NO (V)	--	--	--
CT	2'x4' white textured and off-white fiberglass CTs observed in Rooms 4 to 7.	NO (V)	--	--	--
O	Carpet flooring observed in Room 8.	NO (V)	--	--	--
Roofing	Corrugated metal materials observed on the exterior of the subject building.	NO (V)	--	--	--
O	Uninsulated piping and ductwork was observed throughout the building.	NO (V)	--	--	--
<b>Potential ACM</b>					
Insulating materials	Potential for insulating materials inside hollow metal doors.	Possible	--	--	--



Table 1. Summary of Asbestos Information  
Community Hall  
29 Second Street, Hudson, ON  
December 7, 2017

Material Type <sup>1</sup> (Sample reference #)	Description and Location <sup>2</sup>	Asbestos Containing? (Method) <sup>3</sup>	Asbestos Content and Friability <sup>4</sup>	Condition <sup>4</sup>	Estimated Total Qty <sup>4</sup>
Flooring	<i>Hidden layers of flooring may be present under carpet, top layers of flooring materials or wooden subfloors.</i>	Possible	--	--	--
Caulking and/or sealants	<i>Caulking and/or sealants around windows and doors.</i>	Possible	--	--	--
TSI	<i>Insulating materials may be hidden behind or above solid walls and ceilings. Insulating materials or gaskets may be hidden inside of boilers, furnaces or tanks.</i>	Possible	--	--	--

Notes:

1. TSI = Thermal System Insulation on pipes, fittings and boilers; MJC = Mud Joint Compound associated with finished gypsum board; VFT = Vinyl Floor Tile; CT = Ceiling Tile; VSF = Vinyl Sheet Flooring.
2. Corresponds to room identifier on attached drawings.
3. LA = Samples collected and submitted for laboratory analysis; V = Materials identified by careful visual assessment; R = Reported by site contact to have been installed after 1995.
4. Information only provided for asbestos-containing materials.
5. EA = "Each" individual occurrence of pipe elbows, fittings or other small insulation coverings.
6. **Asbestos-containing material (i.e. 0.5% or more asbestos content) shown in bold font.**
7. *Possible asbestos-containing materials (i.e. materials not sampled in order to maintain the integrity of the building envelope) shown in italics. These materials should be sampled and analyzed for asbestos content prior to any activity that may disturb them (e.g. renovations).*



## Photographs

1263 Innovation Drive, Thunder Bay, ON, P7B 0A2  
Tel: (807) 626-5640 | Fax: (807) 623-5690

[www.truegriteng.com](http://www.truegriteng.com)



COMMUNITY HALL  
29 SECOND STREET, HUDSON, ONTARIO

GENERAL BUILDING PHOTOS



Photo 1: Exterior of Community Hall.



Photo 2: Exterior of Community Hall.



Photo 3: Main Hall – Room #1.



Photo 4: Kitchen – Room #4.

ASBESTOS-CONTAINING MATERIAL



Photo 5: Asbestos-Containing (AC) 9"x9" pink/grey VFT with white streaks (HCH - S2) - Room #3 - Storage room.




Photo 6: AC 9"x9" green/grey VFT with streaks (HCH - S6) - Room #8 - Raised storage room.



Photo 7: AC grey fibrous ceiling boards above the CTs (HCH - S7) - Room #6 - Mens' washroom.



OTHER MATERIALS (NON-ACM AND POTENTIAL ACM)	
	
<p><b>Photo 8: Non-Asbestos Containing (Non-ACM) 12"x12" grey VFT with white streaks (HCH – S1) – Room #1 – Main hall.</b></p>	<p><b>Photo 9: Non-ACM 12"x24" VFT with beige tile pattern (HCH – S3) – Room #4 – Kitchen.</b></p>
	
<p><b>Photo 10: Non-ACM 12"x12" grey VFT with white streaks and flecks (HCH – S4) – Room #7 – Women's washroom.</b></p>	<p><b>Photo 11: Non-ACM MJC associated with finished walls and ceilings (HCH – S5) – Room #5 – Hallway.</b></p>

OTHER MATERIALS (NON-ACM AND POTENTIAL ACM)	
<p><b>Photo 12: Non-ACM black asphalt shingle covering on the exterior walls (HCH – S8) – Exterior.</b></p>	<p><b>Photo 13: Non-ACM wood fibre boards on the walls and ceiling (visual I.D.) – Room #2 – Sports equipment storage room.</b></p>
<p><b>Photo 14: Non-ACM 2'x4' white textured and off-white fibreglass CTs (visual I.D.) – Room #4 – Kitchen.</b></p>	<p><b>Photo 15: Non-ACM corrugated metal materials on the exterior of the subject building (visual I.D.) – Exterior.</b></p>



OTHER MATERIALS (NON-ACM AND POTENTIAL ACM)



Photo 16: Uninsulated piping and ductwork observed throughout the building.



Photo 17: Potential ACM insulating materials inside hollow metal doors – Throughout subject building.





**Field Notes (including a site sketch with sample locations)**


1263 Innovation Drive, Thunder Bay, ON, P7B 0A2

Tel: (807) 626-5640 | Fax: (807) 623-5690

[www.truegriteng.com](http://www.truegriteng.com)



Community Hall, main Floor Plan



NOT TO SCALE

Figure 1. main Floor Sample Locations and General Location of Identified ACM

- LEGEND**
- ① Room Number (Assigned by TGE)
  - S#A-C Asbestos Sample Location
  - XS#A-C Asbestos-Containing Sample Location



**TRUE GRIT**  
ENGINEERING  
1283 Innovation Drive,  
Thunder Bay, ON P7B 0A2

DATE: Dec 7, 2017 PROJECT NO: 17/26615  
DESIGNED BY: L.M./M.B. CHECKED BY:  
PROJECT: Asbestos Audit for 13 municipal Buildings

CLIENT: Municipality of St. James  
LOOKOUT

Community Hall, Second Floor Plan




Figure 2. Second Floor Sample Locations

NOT TO SCALE

LEGEND

- ① Room Number (Assigned by TGE)
- S/A-C Asbestos Sample Location
- \* S/A-C Asbestos-Containing Sample Location

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	① main Hall

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2012
Assessor: LM/MB

Ceiling Height 20' (round)

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
H04-51a	F				X							12x12, grey		X		X				
	F									poured concrete										
	W									wood fibre board (wall)										
	W									plywood										
	C									wood fibre board										
	D									bare ducting										
	D									2 hollow metal doors										

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A

Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	② Sports Equipt. Storage

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: DEC 7, 2017
Assessor: LM/MB

Ceiling Height 7'

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>1</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>3</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
	F								X	poured concrete											
	W								X	wood fibre board											
	C								X	wood fibre board											

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessibile; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	③ storage

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: Lm/m B

Ceiling Height 7'

Room Dimensions  
14'6" x 14'6"  
(4.4191m x 4.4191m)

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
HCH-S2a-c	F								X			pour concrete									
	F				X					9x9, grey + pink with white stripes	19.53	m <sup>2</sup>	X		X	X			H M L		
	W								X	wood fibre board											
	C								X	wood fibre board											

m a s s i f e  
n o t  
A c m

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	④ Kitchen

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/MB

Ceiling Height 7'10"

Room Dimensions


LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
HCH-53a-c	F								X			wood subfloor								
vs4CH-55	F				X					12x24, cream with blue		X								
	W					X	X			2x4, white, textured (fibreglass)	all other 10 tiles		X							
	C							X		2x4, off-white, small bumps (fibreglass)										
	C							X												
above ceiling tiles (above kitchen + washroom area).																				
uninsulated ductwork																				
uninsulated piping (domestic hot water lines)																				
HCH-53a-c ceiling 4x8 sheets of cement (?)											64.3 m <sup>2</sup>	X		X						
↳ (19' + 14.833' + 12.333') x (15')																				
= (46.1663') x (15')																				
= 14.0715m x 4.572m																				
= 64.33 m <sup>2</sup>																				

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

— Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	5 hallway

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: DEC. 7, 2017
Assessor: LM/MB

Ceiling Height 2'10" → 7'

Room Dimensions

VS HCH-54  
VS HCH-55

LOCATION		TYPE OF MATERIAL <sup>2</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
	E								X	wood sf.											
VS HCH-54	F				X					12x12, light grey to brown speck		X									
VS HCH-55	W					X	X					X			X						
	C							X		2x4 white, textured (fibreglass)											

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



# HAZARDOUS MATERIALS SURVEY FORM



**Building Information**

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	6 men's LR

**Project Information**

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/MB

Ceiling Height

Room Dimensions


LOCATION		TYPE OF MATERIAL <sup>2</sup>									Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PEF <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other	F			NF	E	G	F	P	C	V	A	
	F								X		WOOD S.F.										
Hct-S4a	F				X						12x12 light gray w brown specs		X			X					
Hct-S5a,b	W					X	X						X			X					
	C							X			2x4 fiberglass										

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	(7) Women's WR

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec 7, 2017
Assessor: LM/MB

Ceiling Height 7'

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
	F								x			wood s-f.									
HC#-546C	F				x					12x12, light grey w/ brown specs	all	x			x						
	F				x					12x12, cream with blue specs	visually	x			x						
	F				v					12x12, brown with grey specs	sim. lat	x			x						
HC#-550	W					x	x					x			x						
	C							x		2x4, fibreglass											

- Notes:
1. SH = sample; VS (SH) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NDTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

N/A

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	⑧ Raised storage

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/MB

Ceiling Height 71

Room Dimensions  
10' x 10'  
(3.048m x 3.048m)

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
	F								x			wood									
	F								x	carpet (5'x10')											
HA-Sleac	E				x					9'x9" blue + white (5'x10')	4.65m <sup>2</sup>	x		x	x			H M L	mastic not ACM		
	W								x	wood panels											
	W								x	wood fibre board											
	C								x	wood fibre board											

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	main
Room I.D.	9 raised small storage

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/MB

Ceiling Height

Room Dimensions  
5' x 5' 5"  
(1.524m x 1.941m)

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
VS HCH-56	F				x				x			wood	2.96m <sup>2</sup>	x			x				H M L
	W								x	wood fibre board											
	C								x	wood fibre board											
	O								x	bare ducting											

mastic  
not  
acm

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



## Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	second
Room I.D.	(10) m072a=11a0

## Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/MB

Ceiling Height

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>1</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>2</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	E								X			wood plank								
	W								X	wood fibre board										
	C								X	wood fibre board										

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

~~Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.~~ N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



## Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	second
Room I.D.	(#) Mezz. storage

## Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/MB

Ceiling Height
----------------

Room Dimensions
-----------------

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	#								✓			WOOD plank								
	W								X	WOOD plank										
	W								X	WOOD plank										


- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<5% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Community Hall
Building I.D.	29 Second Street, Hudson
Floor	Exterior
Room I.D.	Exterior

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: Lm / m B

Ceiling Height

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>2</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	F W / roof											slab on grade x corrugated metal dome								
	roof over kitchen → sloped ↓ WK																			
HCH	SSac front / back walls									asphalt / shingle covering	58.76 m <sup>2</sup> ↑ (3.759 + 3.302 + 5.79) x 4.572 m									

- Notes:
1. SH = sample; VS (SH) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.  
Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

N/A



**Laboratory Certificate of Analysis**

1263 Innovation Drive, Thunder Bay, ON, P7B 0A2

Tel: (807) 626-5640 | Fax: (807) 623-5690

[www.truegriteng.com](http://www.truegriteng.com)

**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Hudson Community Hall

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
1	Bulk sample identified as "HCH – S1a, vinyl floor tile (VFT), 12"x12", grey with white streaks. [17-09458].  Grey flooring with attached black mastic.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Mastic portion.	NO	--	Non-fibrous	
2	Bulk sample identified as "HCH – S1b, VFT, 12"x12", grey with white streaks. [17-09459].  Grey flooring with attached black mastic.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Mastic portion.	NO	--	Non-fibrous	
3	Bulk sample identified as "HCH – S1c, VFT, 12"x12", grey with white streaks. [17-09460].  Grey flooring with attached black mastic.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Mastic portion.	NO	--	Non-fibrous	

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**


\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.


\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"  
 [#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST:   
 Heather Wilson, B.Sc  
 Industrial Hygiene Scientist

REVIEWED:   
 Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist



**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Hudson Community Hall

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
4	Bulk sample identified as "HCH – S2a, VFT, 9"x9", pink/grey with streaks. [17-09461].  Grey flooring with attached black mastic.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Mastic portion.	NO	--	Non-fibrous	
5	Bulk sample identified as "HCH – S2b, VFT, 9"x9", pink/grey with streaks. [17-09462].  Pink flooring with attached black mastic.				
Layer 1	Flooring portion.	YES	Chrysotile	--	1-10%
Layer 2	Mastic portion.	NO	--	Non-fibrous	
6	Bulk sample identified as "HCH – S2c, VFT, 9"x9", pink/grey with streaks. [17-09463].  Grey flooring with attached black mastic.				
					Note: Sample not analyzed based on positive results for sample #5.

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**

\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.

\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.


**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"

[#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST: 

Heather Wilson, B.Sc  
 Industrial Hygiene Scientist

REVIEWED: 

Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist

**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Hudson Community Hall

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
7	Bulk sample identified as "HCH – S3a, VFT, 12"x24", beige tile pattern. [17-09464].  Beige flooring with grey backing.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Backing portion.	NO	--	Non-fibrous	
8	Bulk sample identified as "HCH – S3b, VFT, 12"x24", beige tile pattern. [17-09465].  Beige flooring with grey backing.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Backing portion.	NO	--	Non-fibrous	
9	Bulk sample identified as "HCH – S3c, VFT, 12"x24", beige tile pattern. [17-09466].  Beige flooring with grey backing.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Backing portion.	NO	--	Non-fibrous	

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**


\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.


\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"  
 [#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST:   
 Heather Wilson, B.Sc  
 Industrial Hygiene Scientist

REVIEWED:   
 Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist

**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Hudson Community Hall

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
10	Bulk sample identified as "HCH – S4a, VFT, 12"x12", grey/brown with white streaks. [17-09467].  Beige flooring with attached beige mastic backing.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Mastic portion.	NO	--	Non-fibrous	
11	Bulk sample identified as "HCH – S4b, VFT, 12"x12", grey/brown with white streaks. [17-09468].  Beige flooring with attached beige mastic backing.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Mastic portion.	NO	--	Non-fibrous	

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**

\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.

\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"  
 [#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST: 

Heather Wilson, B.Sc  
 Industrial Hygiene Scientist

REVIEWED: 

Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist



**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Hudson Community Hall

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
12	Bulk sample identified as "HCH – S4c, VFT, 12"x12", grey/brown with white streaks. [17-09469].  Beige flooring with attached beige mastic backing.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Mastic portion.	NO	--	Non-fibrous	
13	Bulk sample identified as "HCH – S5a, mud joint compound (MJC)". [17-09470].  Firm, white chalky material.	NO	--	Non-fibrous	
14	Bulk sample identified as "HCH – S5b, mud joint compound (MJC)". [17-09471].  Firm, white chalky material.	NO	--	Non-fibrous	
15	Bulk sample identified as "HCH – S5c, mud joint compound (MJC)". [17-09472].  Firm, white chalky material.	NO	--	Non-fibrous	

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**

\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.

\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMM** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"

[#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST: 

Heather Wilson, B.Sc  
 Industrial Hygiene Scientist

REVIEWED: 

Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist

**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Hudson Community Hall

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
16	Bulk sample identified as "HCH – S6a, VFT, 9"x9", green/grey with streaks. [17-09473].  Green flooring with attached black mastic.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Mastic portion.	NO	--	Non-fibrous	
17	Bulk sample identified as "HCH – S6b, VFT, 9"x9", green/grey with streaks. [17-09474].  Grey flooring with attached black mastic.				
Layer 1	Flooring portion.	YES	Chrysotile	--	>75%
Layer 2	Mastic portion.	NO	--	Non-fibrous	
18	Bulk sample identified as "HCH – S6c, VFT, 9"x9", green/grey with streaks. [17-09475].  Grey flooring with attached black mastic.				
					Note: Sample not analyzed based on positive results for Sample #16.
19	Bulk sample identified as "HCH – S7a, ceiling cement boards". [17-09476].  Grey fibrous materials.	YES	Amosite	--	25-50%

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**

\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.

\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"

**[#####]** = TGE sample tracking number

DATE: December 12, 2017

ANALYST: 

Heather Wilson, B.Sc  
 Industrial Hygiene Scientist

REVIEWED: 

Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist

**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Hudson Community Hall

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
20	Bulk sample identified as "HCH – S7b, ceiling cement boards". [17-09477].  Grey fibrous materials.	Note: Sample not analyzed based on positive results for sample #19.			
21	Bulk sample identified as "HCH – S7c, ceiling cement boards". [17-09478].  Grey fibrous materials.	Note: Sample not analyzed based on positive results for sample #19.			
22	Bulk sample identified as "HCH – S8a, asphalt/shingle covering". [17-09479].  Black fibrous asphalt material.	NO	--	Cellulose	10-25%
23	Bulk sample identified as "HCH – S8b, asphalt/shingle covering". [17-09480].  Black fibrous asphalt material.	NO	--	Cellulose	10-25%
24	Bulk sample identified as "HCH – S8c, asphalt/shingle covering". [17-09481].  Black fibrous asphalt material.	NO	--	Cellulose	10-25%

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**


\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.


\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"  
 [#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST:   
 Heather Wilson, B.Sc  
 Industrial Hygiene Scientist

REVIEWED:   
 Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist



Request for Laboratory Services - Chain of Custody



**REPORT TO:**

Company Name: Municipality of Sioux Lookout/ TGE

Contact:

Address:

Phone #: Cell#

Fax #:

Email:

Send results by:  Fax  Mail  Phone  Email

**INVOICE TO:**

Company Name

Contact:

Address:

Phone #: Fax #:

Turn Around Time  REGULAR (3-5 DAYS, DEFAULT)  
 RUSH (24 - 48 HRS, 50% SURCHARGE) BUSINESS HOURS  
 EMERGENCY (<24 HRS OR WEEKEND, 100% SURCHARGE)

(available for Asbestos and Mould analysis only)

TGE Tracking #	Date Collected or Received	Sample Type (Air, Bulk, Dust)	Description (As it will appear on the report)	Analysis Requested						
				Asbestos	Mould	Other (e.g. lead)	Sampling Data (air samples only)			
							Flow Rate (lpm)	Time (minutes)	Volume (litres)	
17-09458	07-Dec-17	bulk	HCH - S1a, VFT, 12x12, grey with white streaks <i>non-fibrous</i>	X						
17-09459	07-Dec-17	bulk	HCH - S1b, VFT, 12x12, grey with white streaks	X						
17-09460	07-Dec-17	bulk	HCH - S1c, VFT, 12x12, grey with white streaks ↓	X						
17-09461	07-Dec-17	bulk	HCH - S2a, VFT, 9x9, pink/grey with white streaks <i>non-fibrous</i>	X						
17-09462	07-Dec-17	bulk	HCH - S2b, VFT, 9x9, pink/grey with white streaks <i>VFT = 1-10% chrys.</i>	X						
17-09463	07-Dec-17	bulk	HCH - S2c, VFT, 9x9, pink/grey with white streaks <i>NO2 analy. 2A</i>	X						
17-09464	07-Dec-17	bulk	HCH - S3a, VFT, 12x24, beige tile pattern <i>non</i>	X						
17-09465	07-Dec-17	bulk	HCH - S3b, VFT, 12x24, beige tile pattern ↓	X						
17-09466	07-Dec-17	bulk	HCH - S3c, VFT, 12x24, beige tile pattern ↓	X						
17-09467	07-Dec-17	bulk	HCH - S4a, VFT, 12x12, grey/brown with white streaks <i>non</i>	X						

**Special Instructions:**  
 Samples will be discarded after 7 days.  
 Please provide a client sample reference (eg. PO #, address, etc.) *Hudson Community Hall, pg.1*  
 Please specify Matrix Code for mould samples only: AN - Allergenco Air; BS - Bulk Sample; TS - Tape Sample; OT - Other Type

Relinquished by: (Please Print) L. Miller	Date: 09-Dec-17	Time: 10:00am	Signature: <i>L. Miller</i>
Accepted by: (Please Print)	Date:	Time:	Signature:
TGE Project #: <i>17-266-15</i>	Date Analyzed: <i>Dec 12, 2017</i>	Time: <i>4:00</i>	Analyst: <i>[Signature]</i>

Request for Laboratory Services - Chain of Custody



**REPORT TO:**

Company Name: Municipality of Sioux Lookout/ TGE

Contact:

Address:

Phone #: Cell#

Fax #:

Email:

Send results by:  Fax  Mail  Phone  Email

**INVOICE TO:**

Company Name

Contact:

Address:

Phone #: Fax #:

Turn Around Time  REGULAR (3-5 DAYS, DEFAULT)  
 RUSH (24 - 48 HRS, 50% SURCHARGE) BUSINESS HOURS  
 EMERGENCY (<24 HRS OR WEEKEND, 100% SURCHARGE)

(available for Asbestos and Mould analysis only)

TGE Tracking #	Date Collected or Received	Sample Type (Air, Bulk, Dust)	Description (As it will appear on the report)	Analysis Requested					
				Asbestos	Mould	Other (e.g. lead)	Sampling Data (air samples only)		
							Flow Rate (lpm)	Time (minutes)	Volume (litres)
17-09468	07-Dec-17	bulk	HCH - S4b, VFT, 12x12, grey/brown with white streaks <i>non</i>	X					
17-09469	07-Dec-17	bulk	HCH - S4c, VFT, 12x12, grey/brown with white streaks <i>"</i>	X					
17-09470	07-Dec-17	bulk	HCH - S5a, MJC	X					
17-09471	07-Dec-17	bulk	HCH - S5b, MJC	X					
17-09472	07-Dec-17	bulk	HCH - S5c, MJC	X					
17-09473	07-Dec-17	bulk	HCH - S6a, VFT, 9x9, green/grey with streaks <i>non</i>	X					
17-09474	07-Dec-17	bulk	HCH - S6b, VFT, 9x9, green/grey with streaks <i>+ve Chry 1-1070</i>	X					
17-09475	07-Dec-17	bulk	HCH - S6c, VFT, 9x9, green/grey with streaks <i>"</i>	X					
17-09476	07-Dec-17	bulk	HCH - S7a, ceiling cement boards <i>25-50% Amos. Lc</i>	X					
17-09477	07-Dec-17	bulk	HCH - S7b, ceiling cement boards	X					

**Special Instructions:**  
 Samples will be discarded after 7 days.  
 Please provide a client sample reference (eg. PO #, address, etc.).  
 Please specify Matrix Code for mould samples only: AN - Allergenco Air; BS - Bulk Sample; TS - Tape Sample; OT - Other Type

*Hudson Community Hall, pg. 2*

Relinquished by: (Please Print) L. Miller	Date: 09-Dec-17	Time: 10:00am	Signature: <i>Laura Miller</i>
Accepted by: (Please Print)	Date:		Signature:
TGE Project #: <i>17-2666-15</i>	Date Analyzed: <i>Dec 12, 2017</i>	Time: <i>4pm</i>	Analyst: <i>N. L. L.</i>



Request for Laboratory Services - Chain of Custody



**REPORT TO:**

Company Name: Municipality of Sioux Lookout/ TGE

Contact:

Address:

Phone #: Cell#

Fax #:

Email:

Send results by:  Fax  Mail  Phone  Email

**INVOICE TO:**

Company Name

Contact:

Address:

Phone #: Fax #:

Turn Around Time  REGULAR (3-5 DAYS, DEFAULT)  
 RUSH (24 - 48 HRS, 50% SURCHARGE) BUSINESS HOURS  
 EMERGENCY (<24 HRS OR WEEKEND, 100% SURCHARGE)  
(available for Asbestos and Mould analysis only)

TGE Tracking #	Date Collected or Received	Sample Type (Air, Bulk, Dust)	Description (As It will appear on the report)	Analysis Requested						
				Asbestos	Mould	Other (e.g. lead)	Sampling Data (air samples only)			
							Flow Rate (lpm)	Time (minutes)	Volume (litres)	
17-09478	07-Dec-17	bulk	HCH - S7c, ceiling cement boards	X						
17-09479	07-Dec-17	bulk	HCH - S8a, asphalt/shingle covering	X						
17-09480	07-Dec-17	bulk	HCH - S8b, asphalt/shingle covering	X						
17-09481	07-Dec-17	bulk	HCH - S8c, asphalt/shingle covering	X						

**Special Instructions:**  
 Samples will be discarded after 7 days.  
 Please provide a client sample reference (eg. PO #, address, etc.).  
 Please specify Matrix Code for mould samples only: AN - Allergenco Air; BS - Bulk Sample; TS - Tape Sample; OT - Other Type

Hudson Community Hall, pg. 3

Relinquished by: (Please Print) L. Miller	Date: 09-Dec-17	Time: 10:00am	Signature: 
Accepted by: (Please Print)	Date:		Signature:
TGE Project #: 17-2666-15	Date Analyzed: Dec 17, 2017	Time: 4pm	Analyst: 





December 19, 2017

Project No. 17-266-15

VIA EMAIL: ([cbo@siouxlookout.ca](mailto:cbo@siouxlookout.ca))

Mr. Jody Brinkman  
Manager of Development Services  
Municipality of Sioux Lookout  
PO Box 158, 25 Fifth Avenue  
Sioux Lookout, ON P8T 1A4

Dear Mr. Brinkman:

**Re: Asbestos Audit  
Lost Lake Centre  
21 Second Street, Hudson, Ontario**

True Grit Engineering (TGE) is pleased to provide to the Municipality of Sioux Lookout the results of a baseline asbestos audit (AA) for the Lost Lake Centre located at 21 Second Street in Hudson, Ontario. The AA was requested by Mr. Jody Brinkman, Manager of Development Services for the Municipality of Sioux Lookout, and TGE understands that it was requested in order to meet the requirement under Ontario Regulation 278/05 (O. Reg. 278/05), *Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations*, for an inventory of asbestos-containing materials (ACM) for the building.

#### **Summary**

ACM were not identified in the subject building and the requirements of O. Reg. 278/05 do not apply. TGE provides recommendations for additional, invasive, investigation in the event of planned renovations.

#### **Background and Methodology**

The Lost Lake Centre is a single storey structure with a below grade poured concrete basement. The construction date is not known for this building; however, it is possible that the building was constructed prior to 1995.

Asbestos was used widely in building materials prior to 1995. Typical asbestos-containing building materials include, but are not limited to, thermal system insulation (TSI), flooring, plaster, stucco, mud joint compound (MJC) associated with finished drywall and ceiling tiles (CT). Building materials containing asbestos can still be purchased for limited applications (e.g. high temperature or corrosive applications); however, asbestos is not expected to be found in most building materials purchased and installed after 1995.

A site visit to the subject building was completed by Mr. Mike Broere, TGE Air Quality Scientist and Ms. Layla Miller, TGE Engineer-in-Training, on December 7, 2017. The site contact was Mr. Richard Fenelon, Facilities Division Supervisor, Municipality of Sioux Lookout. Since this AA was a baseline audit the inspection was minimally invasive and hidden areas, such as those above or behind solid finished ceilings or walls, were viewed where accessible. Samples were not collected where sample collection would compromise the integrity of the subject building or cause unsightly damage to finished surfaces. Additionally, samples were not collected from locations that were not safely accessible (e.g. working at heights).

A visual inspection of functional spaces and rooms in the subject building was conducted to identify materials that could contain asbestos. Potential ACM observed during the site investigation were identified as either friable or non-friable. Friable material is defined in O. Reg. 278/05 as a material that when dry, can be crumbled, pulverized or powdered by hand pressure alone or one that exists in a crumbled, pulverized or powdered state. Additionally, the quantity and condition of potential ACM were noted during the site visit.

Building materials suspected of containing asbestos were collected and sampled in accordance with O. Reg. 278/05. Samples were analyzed via Polarized Light Microscopy (PLM) following the U.S. Environmental Protection Agency Test Method EPA/600/R-93/116: *Method for the Determination of Asbestos in Bulk Building Materials*, June 1993. Where samples consisted of more than one distinct layer (i.e. vinyl floor tile, paper-type backing, mastic, etc.), each layer was analyzed and reported separately.

Materials found to contain 0.5% or more asbestos were identified as ACM (as per O. Reg. 278/05). The attached summary table contains the results of analysis along with the condition, quantity and friability of identified ACM.

### Results

A table of asbestos results, photographs and field notes, including a site plan sketch with sample locations indicated, and a laboratory Certificate of Analysis, are attached. Following is a brief summary of the results of the AA for the subject building:

- ACM were not identified in the Lost Lake Centre.
- ACM may be present in areas of the subject building that were not safely or reasonably accessible (e.g. roofing materials and the interior of wall cavities and ceiling spaces).

### Conclusions and Recommendations

Based on the results of the AA for the Lost Lake Centre, TGE presents the following conclusions and associated recommendations (recommendations are shown in italic font):

- ACM were not identified in the subject building. The requirements of O. Reg. 278/05 do not apply to the subject building; however, the following recommendations are provided to ensure due diligence on the part of the building owner.
- *Keep a copy of this report on site.*
- *Provide a copy of this report to contractors when tendering or completing renovation or demolition work*
- *Prior to beginning any renovations, including demolition, complete a fully invasive AA for the renovation area. In particular, be aware that the following potential ACM may be present:*
  - *insulating material inside of hollow metal doors;*
  - *Insulating materials (e.g. vermiculite) inside attic spaces;*
  - *sealants or caulking materials around windows, doors or equipment penetrations through walls or the roof;*

- *roofing materials and exterior finishes that were not safely accessible;*
- *multiple layers of flooring under carpet, top layers of flooring or wooden subfloors;*
- *insulating material behind or above solid walls and ceilings; and*
- *insulating materials inside pumps, boilers, furnaces, valves, tanks, flanged pipe fittings, motors, transformers, generators or other equipment.*
- *Notify contractors that if, during the course of renovations or demolition, suspected ACM is encountered, all work should cease immediately and the material should be sampled and analyzed to determine whether it contains asbestos.*

#### **Limitations**

The information and data contained in this report, including without limitation, the results of any sampling and analyses conducted by TGE pursuant to its Agreement with the client, have been developed or obtained through the exercise of TGE's professional judgment and are set forth to the best of TGE's knowledge, information and belief. Although every effort has been made to confirm that this information is factual, complete and accurate, TGE makes no guarantees or warranties whatsoever, whether expressed or implied, with respect to such information or data.

The information and data presented in this report are based on the purpose and scope of the project and form the basis for any conclusions and recommendations presented herein. Any conclusions and recommendations presented herein do not preclude the existence of environmental concerns other than those that may have been identified.

Work performed by TGE personnel employed sound environmental assessment principles. TGE cannot guarantee the accuracy and reliability of information provided by others or third parties. Therefore, TGE does not claim responsibility for undisclosed environmental concerns or conditions that may result in costs for environmental clean-up and/or remediation. This report is intended for information purposes only.



Mr. Jody Brinkman  
Municipality of Sioux Lookout  
Asbestos Audit Report - Lost Lake Centre  
Project No. 17-266-15  
December 19, 2017

**Closure**

We trust this is sufficient for your current requirements. If you have any questions or require further information, please do not hesitate to contact the undersigned at 807.285.9005.

Sincerely,

**TRUE GRIT ENGINEERING**

Jacquie Elvish, B.Sc., CRSP  
Senior Health and Safety Specialist  
[jelvish@truegriteng.com](mailto:jelvish@truegriteng.com)

JE/LM/MB:ls

Enclosures:     Table of Asbestos Results  
                     Photographs  
                     Field Notes (including a site sketch with sample locations)  
                     Laboratory Certificate of Analysis





**Table of Asbestos Results for Lost Lake Centre**

1263 Innovation Drive, Thunder Bay, ON, P7B 0A2

Tel: (807) 626-5640 | Fax: (807) 623-5690

[www.truegriteng.com](http://www.truegriteng.com)

Table 1. Summary of Asbestos Information Lost Lake Centre 21 Second Street, Hudson, ON December 7, 2017					
Material Type <sup>1</sup> (Sample reference #)	Description and Location <sup>2</sup>	Asbestos Containing? (Method) <sup>3</sup>	Asbestos Content and Friability <sup>4</sup>	Condition <sup>4</sup>	Estimated Total Qty <sup>4</sup>
Reported date of construction is unknown.					
Identified Asbestos-Containing Materials (ACM)					
No ACM were identified in this building.					
Identified Non-ACM					
VSF (LLC – S1)	Beige VSF with a marble pattern observed in Rooms 3, 4 and 5 (over wooden sub-floor)	NO (LA)	--	--	--
MJC (LLC – S2)	MJC associated with finished gypsum board walls and ceilings observed throughout subject building.	NO (LA)	--	--	--
O (LLC – S3)	Stippled ceiling finish observed on ceiling throughout subject building.	NO (LA)	--	--	--
O	Carpet flooring observed throughout subject building (over wooden sub-floor on the main floor and over poured concrete in the basement).	NO (V)	--	--	--
CT	12"x12", wood fibre CTs observed in Rooms 1 and 16.	NO (V)	--	--	--
CT	2'x4', white wood fibre CT observed in Room 18	NO (V)	--	--	--
O	Uninsulated or foam insulated pipes and ductwork observed throughout the subject building.	NO (V)	--	--	--
O	Pink fibreglass insulation observed in the attic.	NO (V)	--	--	--
Potential ACM					
Insulating materials	Potential for insulating materials inside hollow metal doors.	Possible	--	--	--
Vermiculite	Possible insulating materials in the attic (e.g. vermiculite) may contain asbestos.	Possible	--	--	--
Sealants/caulking	Caulking and/or sealants around windows, doors and roof mounted equipment.	Possible	--	--	--
Roofing and exterior siding	Roofing materials were not safely accessible and these may contain asbestos.	Possible	--	--	--
Multiple Layers of Flooring	There may be additional layers of flooring under existing flooring or carpets or, in some cases, under wooden subfloors.				

Table 1. Summary of Asbestos Information  
Lost Lake Centre  
21 Second Street, Hudson, ON  
December 7, 2017

Material Type <sup>1</sup> (Sample reference #)	Description and Location <sup>2</sup>	Asbestos Containing? (Method) <sup>3</sup>	Asbestos Content and Friability <sup>4</sup>	Condition <sup>4</sup>	Estimated Total Qty <sup>4</sup>
TSI	<i>Insulating materials may be hidden behind or above solid walls and ceilings. Insulating materials or gaskets may be hidden inside of boilers, furnaces or tanks.</i>	Possible	--	--	--

Notes:

1. TSI = Thermal System Insulation on pipes, fittings and boilers; MJC = Mud Joint Compound associated with finished gypsum board; VFT = Vinyl Floor Tile; CT = Ceiling Tile; VSF = Vinyl Sheet Flooring.
2. Corresponds to room identifier on attached drawings.
3. LA = Samples collected and submitted for laboratory analysis; V = Materials identified by careful visual assessment; R = Reported by site contact to have been installed after 1995.
4. Information only provided for asbestos-containing materials.
5. EA = "Each" individual occurrence of pipe elbows, fittings or other small insulation coverings.
6. **Asbestos-containing material (i.e. 0.5% or more asbestos content) shown in bold font.**
7. *Possible asbestos-containing materials (i.e. materials not sampled in order to maintain the integrity of the building envelope) shown in italics. These materials should be sampled and analyzed for asbestos content prior to any activity that may disturb them (e.g. renovations).*



## Photographs

1263 Innovation Drive, Thunder Bay, ON, P7B 0A2  
Tel: (807) 626-5640 | Fax: (807) 623-5690

[www.truegriteng.com](http://www.truegriteng.com)



LOST LAKE CENTRE  
21 SECOND STREET, HUDSON, ONTARIO

GENERAL BUILDING PHOTOS



Photo 1: Exterior of Lost Lake Centre.







Photo 2: Exterior of Lost Lake Centre.







Photo 3: Main entertaining room – Room #2 – Main floor.



Photo 4: Main living room – Room #6 – Main floor.

OTHER MATERIALS (NON-ACM AND POTENTIAL ACM)	
	
<p><b>Photo 5: Non-Asbestos Containing (Non-ACM) beige VSF with a marble pattern (LLC - S1) - Room #3 - Main floor kitchen.</b></p>	<p><b>Photo 6: Non-ACM MJC associated with finished gypsum board walls and ceilings (LLC - S2) - Room #3 - Main floor kitchen.</b></p>
	
<p><b>Photo 7: Non-ACM stippled ceiling finish (LLC - S3) - Room #2 - Main floor entertaining room.</b></p>	<p><b>Photo 8: Non-ACM carpet flooring (visual I.D.) - Room #6 - Main floor living room.</b></p>



OTHER MATERIALS (NON-ACM AND POTENTIAL ACM)	
	
<p><b>Photo 9: Non-ACM 12"x12" wood fibre CTs (visual I.D.) – Room #1 – Main floor entrance.</b></p>	<p><b>Photo 10: Non-ACM 2'x4' wood fibre CTs (visual I.D.) – Room #18 – Basement rec room.</b></p>
	
<p><b>Photo 11: Non-ACM pink fibreglass insulation observed in the attic.</b></p>	<p><b>Photo 12: Non-ACM black foam insulation on piping in basement.</b></p>



OTHER MATERIALS (NON-ACM AND POTENTIAL ACM)



**Photo 13: Potential ACM insulation materials inside hollow metal doors – Throughout subject building.**



**Photo 14: Potential ACM caulking and/or sealants around windows, doors and roof-mounted equipment – Exterior.**



Field Notes (including a site sketch with sample locations)





**TRUE GRIT**  
**ENGINEERING**  
 1283 Innovation Drive,  
 Thunder Bay, ON P7B 0A2

DATE: Dec. 7, 2017 ..... PROJECT NO. 17/26615  
 DESIGNED BY: Lm/mB ..... CHECKED BY: .....  
 PROJECT: Asbestos Audit for 13 Municipal Buildings

CLIENT: Municipality of Stouffville  
 Lookout

Lost Lake Centre, Main Floor Plan




Figure 1. Main Floor Sample Locations


NOT TO SCALE

LEGEND

- ① Room Number (Assigned by TGE)
- S1A-C Asbestos Sample Location
- x S1A-C Asbestos-Containing Sample Location

① Room Number (Assigned by TFE)  
② Static Asbestos Sample Location  
③ Static Asbestos - Containing Sample Location

Figure 2 - Basement Sample Locations  
NOT TO SCALE



Lost Lake Centre, Basement Floor Plan

CLIENT: Municipality of Stouffville  
 1269 Innovation Drive, Thunder Bay, ON P7B 0A2  
**TRUE GRIT ENGINEERING**  
 PROJECT: Asbestos Audit for 13 Municipal Buildings  
 DESIGNED BY: L.M./m.B. CHECKED BY:  
 DATE: Dec. 7, 2017 PROJECT NO: 17-26615

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	① Entrance

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: DEC 7, 2017
Assessor: LM/MB

Ceiling Height 8'

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
VS LLC-52	F								X			carpet								
	F								X	wood s.f.										
	W					X	X					X			X					
	C							X		textured wood s.f. 12"x12" wood fiber CT										
	O								X	3 hollow metal doors										

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.


\* all sampled materials were in good condition throughout \*

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

N/A

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	(2) Open Area (tables)

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 8, 2012
Assessor: LMIME

Ceiling Height 9'

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	F								X			carpet								
	F								X	wood s.f.										
LLC-S2a16	W					X	X					X			X					
LLC-S3a-C	C					X	X			texture coat		X			X					

- Notes:
1. SH = sample; VS (SH) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	② kitchen

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec 7, 2017
Assessor: LM/MB

Ceiling Height 9'

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>1</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>2</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
UC-S1AC	F			X																
	F										X									
UC-S2C	W					X	X													
VS UC-S2	C					X	X													
	O									X										


- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

~~Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.~~  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

N/A

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	④ WR

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec 7, 2017
Assessor: LM/MB

Ceiling Height 8'1"

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>5</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
VS LLC-S1	F			X										X		X				
	F									X										
VS LLC-S2	W					X	X					X		X						
VS LLC-S2	C					X	X					X		X						

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H - high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A

Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	(5) Pantry

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/MB

Ceiling Height 91

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
VS LC-51	F			X										X			X				
	F								X												
VS LC-52	W					X	X						X		X						
VS LC-52	C					X	X						X		X						

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

~~Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.~~ N/A

Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM


**Building Information**

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	Living Room

**Project Information**

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/LMB

Ceiling Height 91

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	CITY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
	F								X			carpet									
	F								X	wood. s.f.											
UC-52d.e	W					X	X					X		X							
UC-53d.e	C					X	X			texture coat		X		X							

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

**NOTE:** for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

~~Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.~~ N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	⑦ Bedroom

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec 7, 2017
Assessor: Lm/mB

Ceiling Height: 91

Room Dimensions


LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>5</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	E								X			carpet								
	E								X	wood J.F										
vs LLC-S2	W					X	X					X			X					
vs LLC-S3	C					X	X			texture coat		X			X					

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	⑧ closet

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec 7, 2017
Assessor: LM/MB

Ceiling Height 9'

Room Dimensions

Sample ID <sup>1</sup>	LOCATION		TYPE OF MATERIAL <sup>3</sup>							Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
	Surface <sup>2</sup>		TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT			Other	F	NF	E	G	F	P	C	V	A
	F									X	carpet										
	F									X	wood S.F										
VS	LLC-S2	W					X	Y													
VS	LLC-S3	C					X	X			texture coat										

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A

Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	(9) Room

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec 7, 2017
Assessor: Lm/mB

Ceiling Height 91

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>2</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
	F								X			carpet									
	F								X	wood sf.											
VS	UC-S2	W				X	X					X		X							
VS	UC-S3	C				X	X			texture coat		X		X							

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

~~Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.~~ N/A

Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



**Building Information**

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	WR # 1

**Project Information**

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/hmB

Ceiling Height: 8'

Room Dimensions

VS  
VS

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>					PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A	
	F								X	carpet											
	F								X	wood sf.											
LLC-52	W					X	X					X			X						
LLC-52	C					X	X					X			X						


- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; Q = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

**NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples**

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	(11) WR #2

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: LM/MB

Ceiling Height 8'

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>1</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>3</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	F								X	carpet										
	F								X	wood S.E.										
VS VS	LLC-SZ	W				X	L					X			X					
	LLC-SZ	C				X	X					X			X					

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

**NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples**

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	main
Room I.D.	(12) Kitchen

### Project Information

Project #: 17-266-15
Client: Corporation of the Municipality of Sioux Lookout
Date: Dec. 7, 2017
Assessor: Cm/m B

Ceiling Height 91

Room Dimensions

	LOCATION		TYPE OF MATERIAL <sup>3</sup>							Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
	Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT			Other	F	NF	E	G	F	P	C	V
		F								X	carpet									
		F								X	wood s.f.									
VS	LLC-S2	W					X	X					X			X				
VS	LLC-S3	C					X	X			texture coat		X			X				
(13) Kitchen Storage																				
		F								X	carpet									
		F								X	wood s.f.									
VS	LLC-S2	W					X	X					X			X				
VS	LLC-S3	C					X	X			texture coat.		X			X				

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed: N/A

Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	basement
Room I.D.	(14) storage.

### Project Information

Project #:	17-21010-15
Client:	Municipality of Sioux Lookout
Date:	DEC. 7, 2017
Assessor:	L.M.M.B.

Ceiling Height
Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>2</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	F								X			P-conc.								
	W								X	ply wood										
	W								X	wood										
	C								X	P-conc.										
	C								X	joists + wood										
	O								X	unins duct work										
		(15) storage/much.																		
	F								X	P-conc.										
	W								X	P-conc.										
	W								X	wood boards										
	C								X	joists + wood										
	O								X	unins piping										
	O								X	unins duct work										
	G								X	fuel oil tank										
	G								X	HWT										
	O								X	furnace										

**Notes:**

- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
- C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
- TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
- F = friable; NF = non-friable
- E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
- C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

**NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples**

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed.  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)

N/A

# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	Lost Lake Centre
Building I.D.	21 Second Street, Hudson
Floor	basement
Room I.D.	(16) Garage

### Project Information

Project #:	17-21616-15
Client:	Municipality of Snow Lake
Date:	Dec. 7, 2017
Assessor:	LM/MB

Ceiling Height

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	F								X			P-conc.								
	W						X			unfinished GB										
	W								X	wood panel										
	W								X	P-conc.										
	C								X	unfinished GB										
	C							X		12x12 wood fibre										
	C								X	wood joists/boards										
			ⓐ storage rm																	
	F								X	P-conc.										
	W						X			unfinished										
	W						X			unfinished										
	C								X	wood										
	O								X	ונים dust nite										

- Notes:
1. S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  2. C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  3. TSI - thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  4. F = friable; NF = non-friable
  5. E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  6. C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed N/A  
 Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



# HAZARDOUS MATERIALS SURVEY FORM



### Building Information

Facility	1st Link Centre
Building I.D.	21 Second Street
Floor	basement
Room I.D.	(18) rec. rm.

### Project Information

Project #:	13-21216-15
Client:	Municipality of GOUX LOOKOUT
Date:	Dec. 7, 2013
Assessor:	LM/MB

Ceiling Height

Room Dimensions

LOCATION		TYPE OF MATERIAL <sup>3</sup>								Comments	QTY	FRIABILITY <sup>4</sup>		CONDITION <sup>5</sup>				PFD <sup>6</sup>		
Sample ID <sup>1</sup>	Surface <sup>2</sup>	TSI (Pipe)	TSI (Other)	VSF	VFT	MJC	Drywall	CT	Other			F	NF	E	G	F	P	C	V	A
	F								X			carpet								
	W								X	wood paneling										
	C							X		wood fibre										
	C						X			unfinished above CT.										
			(18) storage.																	
	F								X	pr-conc.										
	W								X	pr-conc.										
	C								X	wood										
			exterior																	
	F									basement - poured concrete.										
	W								X	corrugated metal siding										
	W								X	metal grating										
			roof cannot view (show)																	

- Notes:
- S# = sample; VS (S#) = visually similar to sample collected elsewhere.
  - C = ceiling; W = Wall; F = Floor; P = Piping; V = vessel; O = Other
  - TSI = thermal system insulation; VSF = vinyl sheet flooring; VFT = vinyl floor tile; MJC = mud joint compound; CT = ceiling tile
  - F = friable; NF = non-friable
  - E = excellent (no damage); G = good (<10% damage); F = fair (<25% damage); P = poor (>25% damage)
  - C = contact/accessible; V = vibration; A = air erosion. Use H = high; M = moderate; L = low.

NOTE: for trowelled and sprayed products sample as follows: <90 sm = 3 samples; >= 90 and < 450 sm = 5 samples; >= 450 sm = 7 samples

Include information on # of fluorescent light fixtures, ballasts checked, lead paint check results, mercury thermostats, smoke detectors observed. N/A

Include information about the type of heating system in place in the building (eg. Forced Air gas, radiant hot water, electric baseboard)



**Laboratory Certificate of Analysis**

1263 Innovation Drive, Thunder Bay, ON, P7B 0A2  
Tel: (807) 626-5640 | Fax: (807) 623-5690

[www.truegriteng.com](http://www.truegriteng.com)

**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Lost Lake Centre, Hudson

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
1	Bulk sample identified as "LLC – S1a, vinyl sheet flooring (VSF) with marble pattern". [17-09445].  Beige flooring with attached fibrous backing and yellow mastic.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Backing portion.	NO	--	MMMF	1-10%
Layer 3	Mastic portion.	NO	--	Non-fibrous	
2	Bulk sample identified as "LLC – S1b, VSF with marble pattern". [17-09446].  Beige flooring with attached fibrous backing and yellow mastic.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Backing portion.	NO	--	MMMF	1-10%
Layer 3	Mastic portion.	NO	--	Non-fibrous	

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**

\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.

\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"

[#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST:

Heather Wilson, B.Sc.  
 Industrial Hygiene Scientist

REVIEWED:

Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist

**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Lost Lake Centre, Hudson

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
3	Bulk sample identified as "LLC – S1c, VSF with marble pattern". [17-09447].  Beige flooring with attached fibrous backing and yellow mastic.				
Layer 1	Flooring portion.	NO	--	Non-fibrous	
Layer 2	Backing portion.	NO	--	MMMMF	1-10%
Layer 3	Mastic portion.	NO	--	Non-fibrous	
4	Bulk sample identified as "LLC – S2a, mud joint compound (MJC)". [17-09448].  Firm, white chalky material	NO	--	Non-fibrous	
5	Bulk sample identified as "LLC – S2b, MJC". [17-09449].  Firm, white chalky material	NO	--	Non-fibrous	
6	Bulk sample identified as "LLC – S2c, MJC". [17-09450].  Firm, white chalky material	NO	--	Non-fibrous	

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**

\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.

\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"

**[#####]** = TGE sample tracking number

DATE: December 12, 2017

ANALYST:



Heather Wilson, B.Sc.  
Industrial Hygiene Scientist

REVIEWED:



Jacquie Elvish, B.Sc., CRSP  
Senior Health and Safety Specialist



**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Lost Lake Centre, Hudson

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
7	Bulk sample identified as "LLC – S2d, MJC". [17-09451].  Firm, white chalky material	NO	--	Non-fibrous	
8	Bulk sample identified as "LLC – S2e, MJC". [17-09452].  Firm, white chalky material	NO	--	Non-fibrous	
9	Bulk sample identified as "LLC – S3a, stippled ceiling". [17-09453].  Firm, white, chalky textured material.	NO	--	Cellulose	1-10%
10	Bulk sample identified as "LLC – S3b, stippled ceiling". [17-09454].  Firm, white, chalky textured material.	NO	--	Cellulose	1-10%

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**

\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.

\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.

**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"

[#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST:



Heather Wilson, B.Sc.  
 Industrial Hygiene Scientist

REVIEWED:



Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist

**Table 1: Fibre Analysis for samples submitted by TGE on behalf of the Municipality of Sioux Lookout**

TGE Reference #: 17-266-15  
 Client Reference: Lost Lake Centre, Hudson

Sample #	Sample description	Asbestos Detected	Type of Asbestos	Non-Asbestos Fibres	Percent* (volume)
11	Bulk sample identified as "LLC – S3c, stippled ceiling". [17-09455].  Firm, white, chalky textured material.	NO	--	Cellulose	1-10%
12	Bulk sample identified as "LLC – S3d, stippled ceiling". [17-09456].  Firm, white, chalky textured material.	NO	--	Cellulose	1-10%
13	Bulk sample identified as "LLC – S3e, stippled ceiling". [17-09457].  Firm, white, chalky textured material.	NO	--	Cellulose	1-10%

**METHOD:** Dispersion Staining with Polarized Light Microscopy (PLM), U.S. Environmental Protection Agency Test Method EPA/600/R-93/116 Method for Determination of Asbestos in Bulk Building Materials, June 1993 as per Ontario Regulation 278/05, November 1, 2005.

**Bulk Asbestos Proficiency Analytical Testing (BAPAT) Participating Laboratory:** True Grit Engineering (TGE) participates in the American Industrial Hygiene Association (AIHA) BAPAT program, laboratory ID 211465.

**NOTES:**

\* Results reported as percent (by volume) of total particulates observed. Results reported for a sample may not total 100%.

\* Ontario Regulation 278/05 defines any material containing 0.5% or more asbestos as an asbestos-containing material.


**MMMMF** (Man-Made Mineral Fibres) may include fibreglass, mineral wool, slag wool, rock wool and ceramic fibres. Synthetic fibres may include; nylon, dacron, orlon, polyester.

**Detection Limit** of this method is approximately 0.5% (percent volume). The symbol for less than is "<" and the symbol for greater than is ">"

[#####] = TGE sample tracking number

DATE: December 12, 2017

ANALYST:   
 Heather Wilson, B.Sc.  
 Industrial Hygiene Scientist

REVIEWED:   
 Jacquie Elvish, B.Sc., CRSP  
 Senior Health and Safety Specialist

Request for Laboratory Services - Chain of Custody



**REPORT TO:**

Company Name: Municipality of Sioux Lookout/ TGE

Contact:

Address:

Phone #: Cell#

Fax #:

Email:

Send results by:  Fax  Mail  Phone  Email

**INVOICE TO:**

Company Name

Contact:

Address:

Phone #: Fax #:

Turn Around Time  REGULAR (3-5 DAYS, DEFAULT)  
 RUSH (24 - 48 HRS, 50% SURCHARGE) BUSINESS HOURS  
 EMERGENCY (<24 HRS OR WEEKEND, 100% SURCHARGE)

(available for Asbestos and Mould analysis only)

TGE Tracking #	Date Collected or Received	Sample Type (Air, Bulk, Dust)	Description (As it will appear on the report)	Analysis Requested						
				Asbestos	Mould	Other (e.g. lead)	Sampling Data (air samples only)			
				Flow Rate (lpm)	Time (minutes)	Volume (litres)				
17-09445	07-Dec-17	bulk	LLC - S1a, VSF, beige with marble pattern <i>flaring + waste → non fib</i>	X						
17-09446	07-Dec-17	bulk	LLC - S1b, VSF, beige with marble pattern <i>backing 1-10% MMMF</i>	X						
17-09447	07-Dec-17	bulk	LLC - S1c, VSF, beige with marble pattern	X						
17-09448	07-Dec-17	bulk	LLC - S2a, MJC <i>non-fibrous</i>	X						
17-09449	07-Dec-17	bulk	LLC - S2b, MJC	X						
17-09450	07-Dec-17	bulk	LLC - S2c, MJC	X						
17-09451	07-Dec-17	bulk	LLC - S2d, MJC	X						
17-09452	07-Dec-17	bulk	LLC - S2e, MJC	X						
17-09453	07-Dec-17	bulk	LLC - S3a, stippled ceiling <i>1-10% cellulose</i>	X						
17-09454	07-Dec-17	bulk	LLC - S3b, stippled ceiling	X						

**Special Instructions:**

Samples will be discarded after 7 days.

Please provide a client sample reference (eg. PO #, address, etc.).

Please specify Matrix Code for mould samples only: AN - Allergenco Air; BS - Bulk Sample; TS - Tape Sample; OT - Other Type

*Lost Lake Centre, Hudson, pg. 1*

Relinquished by: (Please Print) L. Miller Date: 09-Dec-17 Time: 10:00am Signature: *Laura Miller*

Accepted by: (Please Print) Date: Signature:

TGE Project #: *17-2666-15* Date Analyzed: *Dec 12/2017* Time: *1:45 pm* Analyst: *NGL*



Request for Laboratory Services - Chain of Custody



**REPORT TO:**

Company Name: Municipality of Sioux Lookout/ TGE

Contact:

Address:

Phone #: Cell#

Fax #:

Email:

Send results by:  Fax  Mail  Phone  Email

**INVOICE TO:**

Company Name

Contact:

Address:

Phone #: Fax #:

Turn Around Time  REGULAR (3-5 DAYS, DEFAULT)

RUSH (24 - 48 HRS, 50% SURCHARGE) BUSINESS HOURS

(available for Asbestos and Mould analysis only)  EMERGENCY (<24 HRS OR WEEKEND, 100% SURCHARGE)

TGE Tracking #	Date Collected or Received	Sample Type (Air, Bulk, Dust)	Description (As it will appear on the report)	Analysis Requested					
				Asbestos	Mould	Other (e.g. lead)	Sampling Data (air samples only)		
							Flow Rate (lpm)	Time (minutes)	Volume (litres)
17-09455	07-Dec-17	bulk	LLC - S3c, stippled ceiling	X					
17-09456	07-Dec-17	bulk	LLC - S3d, stippled ceiling	X					
17-09457	07-Dec-17	bulk	LLC - S3e, stippled ceiling	X					

**Special Instructions:**  
 Samples will be discarded after 7 days.  
 Please provide a client sample reference (eg. PO #, address, etc.).  
 Please specify Matrix Code for mould samples only: AN - Allergenco Air; BS - Bulk Sample; TS - Tape Sample; OT - Other Type

Lost Lake Centre, Hudson, pg. 2

Relinquished by: (Please Print) L. Miller	Date: 09-Dec-17	Time: 10:00am	Signature: 
Accepted by: (Please Print)	Date:		Signature:
TGE Project #: 17-266-15	Date Analyzed: Dec 12 / 17	Time: 1:45pm	Analyst: 